



Duncan Inspection Services

1224 Cardiff Ct
Modesto, CA 95350
Ph#: (209) 470-7732

Inspection #:	202607-08243	Inspector:	Duncan Lyons
Date:	7/16/2026	Clients Agent:	Michelle Quintong
Dwelling Address:	8200 Jantzen Rd #201 Modesto, CA 95357	Real Estate Company:	Green Valley Homes
Client Name:	Christopher Nall		



We attempt to give the client a comprehensive, clear-cut, unbiased view of the home. The purpose of the inspection is to identify "MAJOR" problems associated with the property although minor items may also be mentioned. Areas that may be of concern to us may not be of concern to the client, and some items that may be of concern to the client may be considered minor to us; therefore, it is advisable to read the entire report. **Where repairs or replacements are suggested, we recommend licensed professionals in that field be called upon to make those repairs.** We advise client to obtain all paperwork from these professionals concerning the work performed. These professionals will be happy to provide you with written statements concerning their work. We further recommend maintaining all paperwork on repairs for future reference. We will perform verification of repairs at an additional fee, upon request.

This inspection does NOT take into account product / component or system recalls. It is beyond the scope of this inspection to determine if any system or component is currently or will be part of any recall in the future. Client may wish to subscribe or contact the Consumer Product safety Commission web site for recall information regarding any system or component.



Duncan Inspection Services
 1224 Cardiff Ct
 Modesto, CA 95350
 Ph#: (209) 470-7732

TABLE OF CONTENTS

SECTION	PAGE
DEFINITION OF TERMS	3
GENERAL INFORMATION	4
GENERAL CONDITIONS	5
Exterior	6
Roof.....	9
Plumbing.....	11
Electrical	12
Heating.....	13
Air Conditioning.....	14
Water Heater	16
Attic.....	17
Crawlspace.....	18
Entry Way / Hall	20
Kitchen.....	21
Bathroom.....	22
Bathroom #2.....	24
Laundry Area	25
Dining Room.....	27
Living Room	28
Bedroom.....	28
Bedroom #2.....	29
Walkthrough Checklist	30
SUMMARY ITEMS	31



Duncan Inspection Services

1224 Cardiff Ct
Modesto, CA 95350
Ph#: (209) 470-7732

DEFINITION OF TERMS

You are encouraged to read all of the pages of your complete inspection report carefully. For the purpose of this report, the directional references to the 'front', 'right', 'left' and 'back' are used to describe sides of the structure as viewed from the street or front of the house; with front being the side facing the road/street. Listed below is a guide to definitions which precede some of the report comments.

Serviceable - The system/item/component is operating properly and/or serving/performing its intended function and is consistent with systems/items/components of like age. In some cases there may be a minor defect (i.e. missing light globe) or maintenance needed and yet still be fully 'Serviceable'.

REVIEW - In the professional opinion of the Inspector the system, item or components was found to be defective, has deficiencies, was inoperable or not fully functional and should be repaired or replaced by a qualified/licensed professional, as necessary, to return to full functionality.

SAFETY - A potential or current safety or health hazard concern exists and requires immediate attention/repairs. The unsafe risk may be due to damage, deterioration, improper installation or a change in accepted residential construction standards and should be properly corrected by a qualified or licensed professional.

REPAIR - This item requires or should be considered for repairs of the system or component now, or as necessary, by a licensed/qualified professional to restore the component to its intended integrity and functionality. Costs associated with necessary repairs may be significant. Damage to inaccessible areas may not be apparent without invasive inspection.

NOT INSPECTED--This system/item/component was not inspected as the fuel/energy source or utility was off, we could not access the item or it was not within the scope or Standards of Practice of an ASHI or NAHI Certified home inspection.

MAINTENANCE - System, item or components are operating properly but may require adjustments, routine maintenance now and in a regular, ongoing manner (which is required on all homes due to normal wear and usage) to ensure proper operation, prevent further deterioration or extend the useful life expectancy.

Observed: Making a visual examination of a system or component and reporting on its condition.

The full report describes each of the structure's systems and also details any recommendations we may have for maintenance or improvements.

***NOTE:** Please understand that the recommendations in our report are just that, recommendations, as we have no legal authority to require anyone to make repairs. Your Real Estate Professional and your real estate purchase contract will guide you in making repair decisions and requests of the property seller's.

This report may contain digital photographs of some items and components. These images are for your convenience only and do not represent all items or components that are or may be deficient. **ALL DEFECTS ARE NOT PHOTOGRAPHED; it is strongly recommended that the entire written Report be reviewed.**



Duncan Inspection Services

1224 Cardiff Ct
Modesto, CA 95350
Ph#: (209) 470-7732

GENERAL INFORMATION

MAJOR SYSTEMS Our evaluation of major systems is both visual and functional provided power and/or fuel is supplied to the component. Identifying or testing for the presence of asbestos, radon, lead-based products, or other potentially hazardous materials is not within the scope of this report. Judging the sufficiency of water flow in plumbing or the cooling efficiency of air conditioning is a subjective evaluation, therefore, we only note a poor condition if, in the inspector's opinion, the adequacy seems to be less than normal. Dismantling and/or extensive inspection of internal components of any appliance, including heaters and heat exchangers, is beyond the scope of this report. The local utility company may conduct such an inspection upon request. There is a time period from inspection to closing that varies with each property. We can only state the condition at time of inspection.

WATER ENTRY AND LEAKS from various causes are common problems that occur from time to time in many houses. It is important that this condition be corrected promptly because it can create a condition where, in addition to possible structural damage, it can promote mold or fungus growth. Exposure to some of these microorganisms that thrive in moist conditions can cause adverse health effects in some people. If past or present water intrusion or staining is noted in this report, corrective action needs to be taken to ensure that the structure is watertight. **The presence and extent of mold is often not visible to the inspector. The presence of, and types of mold, can only be determined by laboratory testing of air and material samplings taken from the house. A mold inspection is not part of this general home inspection, which is non-invasive and unable to see into areas such as wall cavities or under floor coverings. If this is a concern, an inspection for the presence of, and types of, mold should be arranged.**

An information pamphlet that provides general guidelines on health concerns, mold detection and prevention, as well as cleanup of mold-contaminated materials can be obtained at no cost from the California Department of Health Services, (510) 622-4500, or downloaded from their web site, www.cal-iaq.org/mold0107.htm, or from this office.

FUTURE FAILURE: Items in the home can and do experience failure without prior indications. The inspector reports on the condition of the home at the time of inspection. We cannot determine if or when an item will experience failure. Therefore, we cannot be held responsible for future failure.

Carbon monoxide and smoke detectors have been proven to save lives. Client is advised to install carbon monoxide and smoke detectors if not already present in home. Suggest consulting with your local municipality and manufacture specifications as to the proper location and installation of these units.

THIS REPORT CONTAINS IMPORTANT INFORMATION. PLEASE READ IT CAREFULLY.

Duncan Inspection Services**GENERAL CONDITIONS**

1001.	Inspector	Duncan Lyons. NAHI CRI Member # 200456
1002.	In Attendance	Listing Agent. The inspection was performed in accordance with the terms outlined in the Inspection Agreement. The buyer was not present at the time of inspection. As property conditions can change from the date of inspection to the date of closing, it is suggested that the client reference this report during a final walk through.
1003.	Occupancy	The property is vacant. The inspector is unable to determine the period of time this house has been unoccupied. Major systems were reviewed during the home inspection. Plumbing related fixtures, appliances and piping systems were reviewed for appropriate function and leaks, as applicable, at visible areas. However, due to non-use of plumbing and other major systems for a period of time it is important that these systems be reviewed during your final walk-through prior to closing and closely monitored for a few months after occupancy for evidence of leaks and other problems. We recommend you have a professional video sewer inspection performed prior to close. We also suggest monitoring visible areas of subflooring, under showers, commodes and tubs for wet conditions during this same period.
1004.	Property Information	Flat lot. Manufactured home
1005.	Levels	1 story structure.
1006.	Estimated Age	This structure is approximately 58 years of age as stated by the listing agent. We recommend checking local records to verify age. This is not a new structure; therefore it will not be "perfect" and it is likely that a variety of the building techniques no longer used today were applied to some of the components and systems of the building. These techniques are not necessarily 'better' or 'worse' than today's methods, however; the components may not meet today's standards. Since this is not a code inspection, we will focus on fire, health and safety issues. All properties will exhibit some degree of wear and we evaluate property conditions based upon considerations of normal wear for its age and function.
1007.	Weather Conditions	Clear; Warm; Dry. Temperature at the start of inspection was approximately 85.
1008.	Start Time	10:20 AM
1009.	Stop Time	12:00 PM.

Duncan Inspection Services**Exterior**

Our exterior evaluation is visual in nature and is based on our experience and understanding of common building methods and materials. Our review does not take into consideration the normal wear associated with virtually all properties. Clients should routinely observe exterior components and keep them well painted, stained or sealed to prevent deterioration and water entry.

When poorly finished, damaged, decayed or open/unsealed areas exist, or when windows, door, and other through wall openings and projections are not kept well sealed, hidden damage can exist or occur. Our inspection does not include the confirmation of waterproofing flashing. The flashing is concealed behind the exterior siding and is not visible. Inspection of these items would require special arrangements and additional cost.

This inspection of the exposed foundation/structure is not a 'Code Compliance' inspection nor are 'Manufacturer's Specifications' for installation/repairs a part of this inspection. Code compliance/manufacturer's specifications or any product/component or item should be verified through the local building authorities, the company who manufactured the product or item, or with seller prior to closing.

Step #	Component	Comment
1101.	Driveway	Concrete. Common cracks observed, primarily a cosmetic concern. Suggest sealing all concrete slab joints as well as any cracks in concrete/asphalt/brick surfaces to prevent water penetration as a routine maintenance effort.
1102.	Walkways	Concrete. Common cracks observed.
1103.	Exterior Wall Cladding	Siding on this home is covered with metal/vinyl. The inspector is unable to view the condition of covered areas. It is important to keep siding well caulked and sealed to prevent moisture penetration.
1104.	Eaves / Soffits / Fascias	Not Present.
1105.	Trim	
1106.	Window & Frames	Serviceable. Aluminum frame; Vinyl frame; Casement. Double-glazed insulated windows observed in the home. The inspector is unable to determine if all double-glazed insulated windows in this property are completely intact and without compromised seals. Conditions indicating a broken seal are not always visible or present and may not be apparent or visible at the time of inspection. Changing conditions such as temperature, humidity, and lighting limit the ability of the inspector to visually review these windows for broken seals. For more complete information on the condition of all double glazed windows, consult the seller prior to closing. No evidence of damage, deterioration or water penetration was observed. Probing is NOT required when probing would damage any finished surface or where no deterioration is visible. Flashings are covered by the siding and cannot be seen or inspected.

Duncan Inspection Services

1107.	Exterior Door(s)	Metal clad. All door/window/trim junctions should be sealed regularly as these areas can hold water and leak resulting in damage. This is a common maintenance item that is often neglected by homeowners; you should make this a part of your routine seasonal maintenance checklist.
1108.	Gutters / Downspouts	Not Present.
1109.	Fences / Gates	Not Inspected.
1110.	Electrical	Ground Fault Circuit Interrupters (GFCI) may not have been required when the home was built. Suggest client consider upgrading with GFCI's at all receptacles near water sources, such as the kitchen, the bathrooms, the garage, and exterior receptacles to enhance safety. Upgrades should be performed by a licensed electrician.
1111.	Electric Meter(s)	Serviceable. Left side; Main disconnect noted at meter.
1112.	Gas Meter(s)	Serviceable. Located on the left side. Gas shut off located at meter. When gas appliances are present, we suggest that the client install a carbon monoxide detector as a discretionary safety improvement.
1113.	Exterior Faucets	Right. Back flow preventers may not have been required at the time the house was constructed. Recommend client install back flow preventers at all exterior hose bibs as a safety upgrade.
1114.	Sprinkler	Not Inspected.
1115.	Bell / Chime	Not Present.
1116.	Lot / Grade Drainage	Serviceable. Flat lot.
1117.	Foundation / Type	Serviceable. Crawlspace.
1118.	Retaining Wall(s)	Not Present.
1119.	Patio	Not Present.
1120.	Deck	Wood.
1121.	Balcony	Not Present.
1122.	Porch	Not Present.

Duncan Inspection Services

1123. Stairs

Review. Wood. Missing balusters and handrail observed. This is a "Safety Concern". Recommend review by a licensed professional for repair as necessary.

1125. Exterior
Comments

None.

1126. General Safety
& Information

For your personal safety and security: we strongly recommend that all keyed door locks and deadbolts be re-keyed or changed upon your taking possession of this property. Due to this recommendation; such things as loose, missing or improperly working locks/deadbolts may not be mentioned in our reporting. It is important that all windows have properly working locks as a security precaution. If safety latches are, or can be, installed they should be. These latches usually prevent the window from being opened more than 3 or 4-inches. Windows should be checked periodically to make certain that the locks are locked and working. There were no major structural defects observed in the accessible exterior areas of this property, unless otherwise noted in the report.

Duncan Inspection Services**Roof**

Our evaluation of the Roof is performed by walking/climbing onto the roof (unless otherwise noted in the report) to determine if portions are missing and/or deteriorating. Portions of underlayment (tarpaper) and decking are hidden from view and cannot be seen (without removing all of the shingles or tile) during a visual inspection. Leaks are not always visible to the inspector, nor can the inspector determine the watertight integrity of a roof by visual inspection and is NOT a guarantee not to leak in the future. The only way to determine whether a roof is absolutely water tight is to observe it during a period of prolonged rainfall (normally this situation is not present during or prior to our inspection) or to perform a manual water test with water hoses. All roofs may leak under certain weather conditions, such as wind or rain. We CANNOT determine if the roof is installed properly and/or according to manufacturer's specifications and guidelines. As per NAHI and ASHI Standards of Practice, we DO NOT estimate the remaining useful life of the roofing materials. To determine the approximate remaining life left on the roofing materials, we recommend verifying the installation date and manufacturer warranty with the sellers, prior to closing. We recommend any and all roof repairs or replacement be performed by a qualified, licensed roofing contractor. We must develop an opinion about the serviceability of a roof by making certain assumptions about the components we cannot see. We do this based upon the workmanship level and conditions of the things that we can see.

Step #	Component	Comment
1201.	Methods Used To Inspect	Not accessible. Observed from ladder at accessible points. Roof was visually inspected from accessible points on the interior and/or exterior. If a roof is too high, is too steep, is wet, or is composed of materials that can be damaged if walked upon, the roof is not mounted. Therefore, client is advised that this is a limited review and a licensed roofer should be contacted if a more detailed report is desired. The roof was not mounted due to composed of materials that can be damaged if walked upon.
1202.	Material/Type	Metal roofing.
1203.	Exposed Flashings	Serviceable. Metal. Recommend re-sealing all flashings and through the roof vents as a part of routine maintenance.
1204.	Skylights	Not Present.

Duncan Inspection Services

1205. Conditions Roof shows normal wear for its age and type. No damaged, deteriorated, or missing roofing materials were observed; it appears to be in serviceable condition.



1207. Roof This inspection is not a guarantee against the roof leaking. If a roof
Comments guarantee is desired, we suggest having a roofing company perform a
water-test and issue a roof certification.

Duncan Inspection Services

Plumbing

Our focus in the plumbing portion of the inspection is directed at identifying visible water damage and/or problems. We may not always mention common faults such as stuck stoppers or dripping faucets. If considered important, you should check these items independently. Shut-off valves and angle stops under the kitchen or bathroom sinks and toilets are not turned or tested during the inspection due to the possibility of leaking. All shut-off valves or angle stops should be turned regularly to ensure free movement in case of emergency. The water supply system was tested for its ability to deliver functional water pressure to installed plumbing fixtures and the condition of connected piping that was visible.

Step #	Component	Comment
1501.	Water Supply System	Water supply appears to be connected to the public system.
1502.	Shut Off Valve Location	Main shut-off is located at the right side. Since main shut-off valves are operated infrequently, it is not unusual for them to become frozen over time. They often leak or break when operated after a period of inactivity. For this reason main shut-off valves are not tested during a home inspection. We suggest caution when operating shut-offs that have not been turned for a long period of time. All shut-off valves and angle stops should be turned regularly to ensure free movement in case of emergency.
1503.	Water Pressure	Not Tested.
1504.	Supply Lines	Galvanized. Galvanized water lines rust from the inside out and can become restricted over time. When low water flow is observed at plumbing fixtures, some restriction may have occurred. We suggest further review by a licensed plumbing contractor prior to closing for repairs/replacement as needed to ensure proper water flow.
1505.	Drain Waste Lines & Vent Pipes	Serviceable. ABS; As visible. Only accessible/visible plumbing can be reviewed. All plumbing waste lines are tested by running each fixture's water into the sewage system. No solids are put into the system. We suggest the Customer consult with the Seller regarding any potential in-house, sewer or septic line blockage history. There were no waste or drain line leaks observed, unless otherwise noted in this report.
1506.	Waste Disposal System	The waste disposal system appears to be connected to public sewer systems. Because of isolated instances where they system has not been connected to the public sewer system but remains an on-site system, client may wish to confirm sewer connection with the local building department or the property owner prior to closing.
1509.	Plumbing Comments	Comment. As of January 1 2017 all home in California are required to have water saving faucets, shower heads and toilets. Although testing and measuring the flow rate at the plumbing fixtures is not within the scope of this inspection, it is the inspectors opinion that some or all of the fixtures in this house DO NOT meet this requirement. Replacement of all these plumbing fixtures may be costly.

Duncan Inspection Services**Electrical**

Our review of the electrical system is limited to that which is visible and accessible at the time of inspection. Determining the actual capacity of the system requires load calculations, which are not within the scope of this report. Underground circuits and concealed components of the system are not inspected.

Step #	Component	Comment
1601.	Main Service Drop	Service entrance is underground; Service entrance cables are not visible.
1602.	Main Electrical Panel	The main electrical panel is located in left side. Electrical disconnect is present. System appears to be properly grounded.
1603.	Main Panel Comments	None.
1604.	Wiring Method	Romex. Lighting branch circuit wiring is copper.
1605.	Service Amperage and Voltage	120 & 240 volts; Less than 100 amps. Service panel rating is approximately 70 amps. When a service panel rating is under 100 amps, an upgrade may be required if more or higher demand electric appliances are to be added. The system was standard at the time of construction and, unless otherwise noted, appears to be serviceable. Client should consult with a licensed electrician if this is a concern or if additions are planned.
1606.	Sub-Panel Comments	Serviceable. The sub-panel(s) is located in master bedroom closet.



1607.	Smoke Detectors	Review. None observed, suggest installing smoke detectors, as necessary, for safety.
-------	-----------------	---

Duncan Inspection Services

1608.	Carbon Monoxide Detectors	Review. No carbon monoxide detector(s) noted. We recommend installing carbon monoxide detectors according to manufacturer's specifications and local ordinances to provide protection to occupants from potential poisoning from fossil fuel burning appliances, including fireplaces.
1610.	Electrical Comments	None.
1611.	Alarm system	Not Present.

Heating

Our evaluation of major systems is both visual and functional provided power and/or fuel is supplied to the component. Identifying or testing for the presence of asbestos, radon, lead based products, or other potentially hazardous materials is not within the scope of this report. Judging the adequacy of the cooling efficiency of air conditioning and heating is a subjective evaluation, therefore, we only note a poor condition if, in the inspector's opinion, the adequacy seems less than normal. We urge you to evaluate these systems prior to closing. DISMANTLING AND/OR EXTENSIVE INSPECTION OF INTERNAL COMPONENTS OF ANY APPLIANCE, INCLUDING HEATERS AND HEAT EXCHANGERS, IS BEYOND THE SCOPE OF THIS REPORT. THE LOCAL UTILITY COMPANY MAY CONDUCT SUCH AN INSPECTION UPON REQUEST.

Step #	Component	Comment
1701.	Location of unit	The heating system is located in exterior right.
1702.	Heating System Design Type/Brand	Gas forced air. Due to inaccessibility of many of the components of this unit, the review is limited. Unit was tested using normal operating controls and appeared to function properly at time of inspection. Holes or cracks in the heat exchanger are not within the scope of this inspection as heat exchangers are not visible or accessible to the inspector. If a detailed inspection is desired, a licensed heating contractor should be consulted prior to closing to ensure proper and safe operation of this unit.
1703.	Energy Source	Natural gas; Shutoff valve provided.
1704.	Burner Chambers	Unable to inspect heat exchanger due to closed system.
1705.	General Conditions	The furnace was tested using normal operating controls and appeared to function properly at time of inspection.
1706.	Exhaust Venting	Serviceable. Metal; Where visible.
1707.	Thermostat	Serviceable. The thermostat is located at the hall.

Duncan Inspection Services

1708.	Air Filters	We recommend changing or cleaning the filter monthly during the heating/cooling season.
1709.	Distribution / Ducting	Ducts/Registers. Heat is supplied by a duct system. The adequacy, efficiency or even distribution of air throughout a building cannot be addressed by a visual inspection. The inspector does not perform pressurization or smoke tests on the duct system. As a result, no representation is made regarding the duct systems compliance with Title 24 of the California Energy Efficiency Standards for Residential and Nonresidential Buildings. Normal servicing and maintenance is recommended on a yearly basis to ensure that duct leakage is held to a minimum. Ducts are a source of indoor air quality contamination and should be cleaned periodical as an investment in your personal environmental hygiene. Environmental evaluations are beyond the scope of this inspection, if you are concerned with the indoor air quality we recommend contacting a member of the American Society of Industrial Hygienist to perform air quality testing.
1712.	Heating Comments	None.

Air Conditioning

Our evaluation of major systems is both visual and functional provided power and/or fuel is supplied to the component. Judging the adequacy of the cooling efficiency of air conditioning and heating is a subjective evaluation, therefore, we only note a poor condition if, in the inspector's opinion, the adequacy seems less than normal. We urge you to evaluate these systems prior to closing.
DISMANTLING AND/OR EXTENSIVE INSPECTION OF INTERNAL COMPONENTS OF ANY APPLIANCE IS NOT WITHIN THE SCOPE OF THIS INSPECTION.

Step #	Component	Comment
1801.	Location of unit	The Air conditioning system is located at the right side
1802.	Air Conditioning Design Type/Brand	Split system.
1803.	General Conditions	The air conditioner was activated to check the operation of the motor and the compressor, both of which appear to be in serviceable condition. As a detailed review of the cooling capacity of this unit is beyond the scope of this inspection, we make no warranty as to the system's adequacy.

Duncan Inspection Services

1804.	Temperature Difference	Temperature at return register was 86 degrees; temperature at supply was 66 degrees, a difference of degrees that is in the 14 to 22 degree normal operating range. Unit functioned properly when tested and appeared to be serviceable at time of inspection.
1805.	Energy Source	Electric with disconnect provided.
1806.	Air Filters	We recommend changing or cleaning the filter monthly during the heating/cooling season.
1807.	Distribution / Ducting	Ducts/Registers. The adequacy, efficiency or even distribution of air throughout a building cannot be addressed by a visual inspection. The inspector does not perform pressurization or smoke tests on the duct system. As a result, no representation is made regarding the duct systems compliance with Title 24 of the California Energy Efficiency Standards for Residential and Nonresidential Buildings. Normal servicing and maintenance is recommended on a yearly basis to ensure that duct leakage is held to a minimum.
1808.	Thermostat	Serviceable. The thermostat is located at the hall.
1810.	Air Conditioning Comments	For several years, the minimum efficiency standard for newly-manufactured HVAC equipment has been 10 SEER (Seasonal Energy Efficiency Ratio). On January 23, 2006, the law has required manufactures to stop producing anything less than a 13 SEER. Once there are no remaining 10 SEER parts, if the outside unit rated 10 SEER or lower needs to be replaced it will be necessary to upgrade to a 13 SEER unit. This may require a modification to the inside unit to ensure proper compatibility between the inside unit and outside unit. How contractors go about making the two units compatible can vary, depending primarily on the age of a system. Complying with 13 SEER may mean spending more upfront, but the energy savings add up to smaller energy bills going forward. Once your home is 13 SEER efficient, it's likely you'll see real savings on your monthly utility bill. Actual savings will vary depending on the age, efficiency, usage and condition of the unit. Additional information is available at www.doe.gov or www.13seersolutions.com

Duncan Inspection Services

Water Heater

Since a temperature pressure relief valve is operated infrequently, it is not unusual for them to leak or break when operated after a period of inactivity. For this reason the TPR valve is not tested during a home inspection. We suggest caution when operating TPR valves that have not been tested for a long period of time. When installed new the TPR valve should be tested regularly to ensure free movement in case of emergency. In some cases the water heater is covered with an insulated blanket; when this is noted client is informed that the review of the water heater is limited.

Inspection performed at water heaters represents a general review of their apparent operational behavior without dismantling, not a detailed inspection of unobservable internal components and their condition.

Water heaters should be drained periodically. Burners should be cleaned and adjusted for efficient operation. We also recommend that all safety and drain valves be checked during regular heater maintenance. Reduced settings will usually result in extended life and reduced operating cost.

Step #	Component	Comment
2101.	Location of unit	The water heater is located in the exterior right.
2102.	Brand / Capacity / Age	40 gallon. Manufactured by Rheem. Per label, manufacture date of this unit is in 2018.
2103.	Supply Lines	Galvanized. Galvanized water lines rust from the inside out and can become restricted over time. When low water flow is observed at plumbing fixtures, some restriction may have occurred. We suggest further review by a licensed plumbing contractor prior to closing for repairs/replacement as needed to ensure proper water flow.
2104.	Energy Source	Gas shut-off valve was observed near this appliance.
2105.	Temperature / Pressure Release Valve	Serviceable.
2106.	Combustion Chamber	Closed System. Unable to inspect combustion chamber due to closed system.
2107.	Water Heater Condition	The water heater appears to be properly strapped for earthquake safety.
2108.	Flue Venting	Serviceable. Metal; Where visible.
2109.	Overflow Pan / Drain Line	Not Present. Water heater is located indoors or in an area where damage can occur without an overflow pan/drain line. This may not have been required when the home was built. Suggest client consider installing an overflow pan and drain line as an upgrade.
2110.	Water Heater Comments	None.

Duncan Inspection Services**Attic**

Entering attics that are heavily insulated can cause damage to the insulation and attic framing. Attics with deep insulation cannot be safely inspected due to limited visibility of the framing members upon which the inspector must walk. In such cases, the attic is only partially accessed, thereby limiting the review of the attic area from the hatch area only. Inspectors will not crawl the attic area when they believe it is a danger to them or that they might damage the attic insulation or framing.

The primary scope of this inspection identifies evidence of past or current leakage, the presence of insulation and types of ventilation and a visual review of the structural components. Our examination of the structural components is a review of the visual components and is not a technically exhaustive examination.

Water stains around roof penetrations such as chimneys and plumbing vents are very common. It is usually impractical to determine if these stains are active unless they are leaking at the time of the inspection thus when stains are present further monitoring is advised. Viewing during a rain storm and extensive moisture testing would increase the chances of determining whether leaks exist or the current status of staining. Older roofs are, of course, more prone to water infiltration but new roofs can develop leaks as well. Regular monitoring and maintenance of all roofs is advised. We suggest checking roof surfaces each spring and fall and after each severe storm.

Most homes can benefit from additional insulation. The Department of Energy website at www.eren.doe.gov/consumerinfo can help you determine recommended upgrades and the payback period for insulation improvements.

Step #	Component	Comment
2201.	Access location / Inspection method	Due to the construction design of this house, the space between the ceiling and roof was not visually inspected, as this area is not visible or accessible to the inspector. If client has concerns regarding this area of the home, a specialist should be contacted for further evaluation and information.

Duncan Inspection Services

Crawlspace

Water seepage and moisture penetration are common problems in crawlspaces usually resulting from inadequate water management above ground. Improving drainage and grading can correct most causes. Our review of the crawlspace cannot always detect the past or future possibility of water in this area. If you are concerned about this possibility, we suggest that you inquire with the owner. NOTE: The presence of a sump pump can suggest water has or may enter the crawlspace. Most causes of moisture or water penetration at the foundation can be corrected by improving the drainage at the exterior. Prolonged or heavy rains may occasionally bring seepage. Moisture in a crawlspace can promote wood decay, therefore crawlspaces should be adequately ventilated and vents should be left open year round.

Step #	Component	Comment
2301.	Methods Used To Inspect	The crawlspace was accessed from the exterior hatch. Crawlspace access cover is missing/damaged. Repair/replace as needed to prevent unwanted entry into crawlspace.
2302.	Floor	Concrete; Dirt.
2303.	Walls	Review. Metal skirting. Damaged areas observed. Recommend review by a licensed/qualified professional for repair or replacement as necessary.
2304.	Joists	Not Present.
2305.	Sub Floor	Particle board; Plywood. Limited review due to vapor barrier, client is advised to verify condition with sellers prior to close.
2306.	Support Posts / Columns	Review. Concrete blocks; Wood. Wood rot, moisture damage observed under bathroom area, review by a licensed professional is needed for corrections as needed prior to close.



2307.	Beams	Metal.
-------	-------	--------

Duncan Inspection Services

2308.	Electrical	Serviceable.
2309.	Ventilation	Serviceable.
2310.	Insulation	Review. Rolled/batt insulation. Loose/missing sections observed in crawlspace, suggest securing or replacement as necessary.
2311.	Vapor Barrier	Serviceable.
2312.	Distribution / Ducting	Ducts/Registers.
2313.	Visible Plumbing	Review. ABS; Galvanized. Leaking observed at bathroom. Recommend review by a licensed plumber for repair or replacement, as necessary.



2315.	Crawlspace	None.
	Comments	
2316.	Sump Pit	Not Present.
2317.	Sump Plumbing	Not Present.
2318.	Ejector Pump	Not Present.

Duncan Inspection Services**Entry Way / Hall**

Our interior review is visual and evaluated with similar aged homes in mind. Cosmetic considerations and minor flaws such as a torn screen or an occasional cracked window can be overlooked, thus we suggest you double-check these items, if concerned. Inspections are limited to visible and/or accessible areas. Personal belongings and furniture restrict access to receptacles, windows, walls, and flooring. All accessible areas are checked as noted in report. Note: As pointed out in the inspection agreement, materials regularly used in residential construction may contain potentially hazardous substances such as asbestos and formaldehyde. Our report will not identify those substances since laboratory testing is necessary to detect their presence.

Step #	Component	Comment
3001.	Floors	Vinyl.
3002.	Walls	Serviceable. Paneled. Fresh paint observed in several locations throughout home. Suggest client consult with seller for any information regarding the condition of walls and ceilings prior to painting, such as staining, growth, or any other damage.
3003.	Ceilings	Serviceable. Paneling.
3004.	Doors	Serviceable. Wood.
3005.	Closet / Wardrobe	Not Present.
3006.	Windows	Serviceable. Vinyl frame. Double-glazed insulated windows observed in the home. The inspector is unable to determine if all double-glazed insulated windows in this property are completely intact and without compromised seals. Conditions indicating a broken seal are not always visible or present and may not be apparent or visible at the time of inspection.
3007.	Heat / Cooling Source	Not Present.
3008.	Electrical	Serviceable.
3009.	Stairs	Not Present.
3011.	Entry Way / Hall Comments	None.

Duncan Inspection Services

Kitchen

The kitchen inspection is a combination of visual and functional. Appliances are operated, if power is supplied. Calibrations to cooking systems are not evaluated nor life expectancies given to dishwashers. Note: Dishwashers can fail at any time due to their complexity. Our review is to determine if the system is free of leaks and excessive corrosion.

Step #	Component	Comment
3101.	Floor	Vinyl.
3102.	Walls	Serviceable. Paneled.
3103.	Ceiling	Serviceable. Paneling.
3104.	Ceiling fan	Not Present.
3105.	Doors	Not Present.
3106.	Windows	Serviceable. Aluminum frame.
3107.	Heat / Cooling Source	Serviceable. Central heating/cooling.
3108.	Electrical	Review. Ground Fault Circuit Interrupters (GFCI) may not have been required when the home was built. Suggest client consider upgrading with GFCI's at all receptacles near water sources, such as the kitchen, the bathrooms, the garage, and exterior receptacles to enhance safety. Upgrades should be performed by a licensed electrician.
3109.	Cabinets	Serviceable.
3110.	Counter Tops	Serviceable. Polished granite. Suggest caulking as necessary.
3111.	Sinks	Serviceable.
3112.	Faucets	Serviceable.
3113.	Traps / Drains / Supply	Serviceable. Flow and drainage were serviceable at the time of inspection.
3114.	Disposals	Serviceable. The disposal was operative. The disposal power cord was safely wired and clamped at the base of the unit.
3115.	Dishwasher(s)	Make: General Electric. Dishwasher was operational at the time of inspection. Dishwashers most commonly fail internally at the pump, motor or seals. We do not disassemble these units to inspect these components. Our inspection is limited to operating the unit on the 'normal wash' cycle only. We recommend you operate this unit prior to closing.
3117.	Stove / Cook Top	Serviceable. Freestanding; Gas (with shutoff valve).
3118.	Ovens	Serviceable. Gas (with shutoff valve).
3119.	Hood / Fan / Light	Serviceable. Exterior vented.
3120.	Microwave	Not Present.
3121.	Pantry/Closet	Not Present.
3123.	Comments	None.

Duncan Inspection Services

Bathroom

Our focus in bathrooms is directed at identifying visible water damage and/or problems. We may not always mention common faults such as stuck stoppers or dripping faucets. If considered important, you should check these items independently. Shut-off valves and angle stops under kitchen or bathroom sinks and toilets are not turned or tested during the inspection due to the possibility of causing a leak. All shut-off valves or angle stops should be turned regularly by the homeowner to ensure free movement in case of emergency.

Step #	Component	Comment
3201.	Location	Master Bath.
3202.	Floor	Serviceable. Vinyl
3203.	Walls	Serviceable. Paneled.
3204.	Ceiling	Serviceable. Paneling.
3205.	Doors	Serviceable. Hollow core.
3206.	Closet / Wardrobe	Not Present.
3207.	Windows	Serviceable. Aluminum frame.
3208.	Heat / Cooling Source	Central heating/cooling. Air register is missing, replacement is needed.
3209.	Electrical	Ground Fault Circuit Interrupters (GFCI) may not have been required when the home was built. Suggest client consider upgrading with GFCI's at all receptacles near water sources, such as the kitchen, the bathrooms, the garage, and exterior receptacles to enhance safety. Upgrades should be performed by a licensed electrician.
3210.	Exhaust Fan	Cover is missing. Suggest repairs/replacements as needed.



Duncan Inspection Services

3211.	Tub/Whirlpool	Not Present.
3212.	Tub Surround	Not Present.
3213.	Tub Enclosure	Not Present.
3214.	Tub Faucet	Not Present.
3215.	Shower Base	Serviceable. Shower pans are not filled and tested for leaks during the inspection as this is a visible inspection of accessible areas only. Visible examination of the shower pan and surrounding areas was inspected for leaks. No visible leaks were noted at the time of the inspection.
3216.	Shower Surround	Serviceable. Plastic. Suggest all edges and tub/shower walls be caulked and sealed to prevent moisture penetration. Failure to keep walls sealed can cause deterioration and extensive moisture damage to the interior walls and surrounding sub-flooring. This damage is not always visible or accessible to the inspector at the time of inspection.
3217.	Shower Door	Serviceable. Tempered safety glass installed for safety.
3218.	Shower Faucet	Serviceable.
3219.	Sinks	Serviceable. The sinks were filled. No damage or evidence of leaking was observed.
3220.	Sink Faucets	Serviceable.
3221.	Traps / Drains / Supply	Serviceable. Flow and drainage were serviceable at the time of inspection.
3222.	Toilet	Review. The toilet bowl is loose at floor anchor bolts. The wax ring inside the unit must have a snug, secure fit in order to keep from leaking. Properly resealing and re-securing this unit is suggested to prevent water leakage and damage to the sub-floor area. This type of damage is not always visible or accessible to the inspector at time of inspection. Recommend review by a qualified plumber for repair or replacement, as necessary.
3223.	Counter / Cabinets	Serviceable. Polished granite. Suggest caulking as necessary.
3227.	Bathroom Comments	None.

Duncan Inspection Services**Bathroom #2**

Step #	Component	Comment
3201.2.	Location	Hall.
3202.2.	Floor	Serviceable. Vinyl
3203.2.	Walls	Serviceable. Paneled.
3204.2.	Ceiling	Serviceable. Paneling.
3205.2.	Doors	Serviceable. Hollow core.
3206.2.	Closet / Wardrobe	Not Present.
3207.2.	Windows	Serviceable. Aluminum frame.
3208.2.	Heat / Cooling Source	Serviceable. Central heating/cooling.
3209.2.	Electrical	Ground Fault Circuit Interrupters (GFCI) may not have been required when the home was built. Suggest client consider upgrading with GFCI's at all receptacles near water sources, such as the kitchen, the bathrooms, the garage, and exterior receptacles to enhance safety. Upgrades should be performed by a licensed electrician.
3210.2.	Exhaust Fan	Not Present.
3211.2.	Tub/Whirlpool	Serviceable. Tub.
3212.2.	Tub Surround	Serviceable. Plastic.
3213.2.	Tub Enclosure	Not Present.
3214.2.	Tub Faucet	Serviceable.
3215.2.	Shower Base	Serviceable. Tub.
3216.2.	Shower Surround	Serviceable. Plastic. Suggest all edges and tub/shower walls be caulked and sealed to prevent moisture penetration. Failure to keep walls sealed can cause deterioration and extensive moisture damage to the interior walls and surrounding sub-flooring. This damage is not always visible or accessible to the inspector at the time of inspection.
3217.2.	Shower Door	Not Present.
3218.2.	Shower Faucet	Serviceable.
3219.2.	Sinks	Serviceable. The sinks were filled. No damage or evidence of leaking was observed.
3220.2.	Sink Faucets	Serviceable.
3221.2.	Traps / Drains / Supply	Serviceable. Flow and drainage were serviceable at the time of inspection.
3222.2.	Toilet	Serviceable. The toilet flushed and drained properly and there was no evidence of leaking at time of inspection.
3223.2.	Counter / Cabinets	Serviceable. Polished granite. Suggest caulking as necessary.
3227.2.	Bathroom Comments	None.

Duncan Inspection Services

Laundry Area

The supply hoses to the washer are not disconnected during the inspection, nor are the valves operated. These can leak at any time and should be considered a part of normal maintenance. To avoid floor damage, the washer and dryer are not moved if present during the inspection. Therefore, a limited review of area behind washer/dryer is conducted. We recommend checking this area once the machines have been removed, prior to close of escrow. It is beyond the scope of the inspection to inspect the washer and dryer. If these appliances are included in the sale of the property, we suggest consulting the sellers as to proper operation prior to close. We suggest that you clean exhaust pipes upon occupancy and then regularly to enhance safety/performance.

Water hoses that discharge into laundry tubs can cause contamination by creating a 'cross connection' if they discharge below the tub rim. We suggest you keep these elevated above the flood rim of the tub.

Step #	Component	Comment
3401.	Floor	Serviceable. Vinyl
3402.	Walls	Review. Paneled. Moisture damaged trim and wall observed. The extent of damage could not be determined without destructive analysis (maintenance and/or repairs should be performed). Suggest reviewing latest pest control report for a more detailed evaluation. See page 4 of full report for further information regarding water entry and growth.



3403.	Ceiling	Serviceable. Paneling.
3404.	Doors	Serviceable. Hollow core.
3405.	Closet / Wardrobe	Serviceable. Hollow core.
3407.	Cabinets	Serviceable.

Duncan Inspection Services

3408.	Laundry Tub / Sink	Not Present.
3409.	Faucets	Not Present.
3410.	Heat / Cooling Source	Not Present.
3411.	Electrical	Serviceable.
3412.	Washer Hookups	Washer hook-ups observed. No washing machine was present at the time of inspection, therefore, no test was performed on the washer drain line to determine if line was draining properly. This was a visible inspection of this area only. No guarantee or warranty is given on the future of this drainage system, as drain lines can become blocked at any time without warning.
3413.	Dryer Hookups	Serviceable. Electric. 220/240 Volt outlet observed with current provide to both legs. It is beyond the scope of this inspection to test voltage.
3414.	Exhaust Fan	Not Present.
3416.	Laundry Area Comments	None.
3417.	General information	A few ideas to improve or get the optimal energy efficiency are: 1) set the wash temperature to cold instead of hot and save 50% on energy, 2) wash only full loads, 3) dry towels and heavy articles in separate loads, 4) do not overload or over-dry clothing, 5) clean the lint trap after every load to improve circulation, 6) do all of your laundry at once to take advantage of an already warm dryer, 7) use a cool-down cycle to finish drying clothing with residual dryer heat. *NOTE: Energy and water savings can be achieved by using a front loader washer and cold water. Many of today's detergents are designed to be most effective with less water and cold water. We suggest the Customer consider upgrading to a metal exhaust vent pipe for the dryer instead of flexible plastic or mylar ducting; which has been implicated in house fires. The use of metal ducts is now the widely accepted standard, recommended by the Underwriters Laboratory, Association of Home Appliance Manufacturers, the Consumer Products Safety Commission and all dryer manufacturers and most city building codes. The use of an all-metal (rigid or semi-rigid) dryer exhaust duct helps to achieve optimal air flow, reducing lint build-up and extending the life of the dryer, due to lower operating temperatures.

Duncan Inspection Services**Dining Room**

Step #	Component	Comment
3521.	Floors	Serviceable. Vinyl.
3522.	Walls	Serviceable. Paneled.
3523.	Ceilings	Serviceable. Paneling.
3524.	Ceiling fan	Not Present.
3525.	Doors	Not Present.
3526.	Closet / Wardrobe	Not Present.
3527.	Windows	Review. Dry rot observed at window sill. Recommend further review for repair as necessary.



3528.	Heat / Cooling Source	Serviceable. Central heating/cooling.
3529.	Electrical	Serviceable.
3531.	Dining Room Comments	None.

Duncan Inspection Services**Living Room**

Step #	Component	Comment
3541.	Floors	Vinyl.
3542.	Walls	Serviceable. Paneled.
3543.	Ceilings	Serviceable. Paneling.
3544.	Ceiling fan	Not Present.
3545.	Doors	Not Present.
3546.	Closet / Wardrobe	Not Present.
3547.	Windows	Review. Aluminum frame; Vinyl frame. Double-glazed insulated. Window lock(s) is missing at driveway side window. Corrections are needed for security.
3548.	Heat / Cooling Source	Serviceable. Central heating/cooling.
3549.	Electrical	Review. Ungrounded receptacles observed in the living room. Suggest review by licensed electrical contractor for repairs/replacements as needed to ensure safety.
3551.	Living Room Comments	None.

Bedroom

Step #	Component	Comment
3581.	Location	Left rear; Master Bedroom.
3582.	Floors	Serviceable. Vinyl.
3583.	Walls	Serviceable. Paneled.
3584.	Ceilings	Serviceable. Paneling.
3585.	Ceiling fan	Not Present.
3586.	Doors	Serviceable. Hollow core.
3587.	Closet / Wardrobe	Serviceable. Hollow core.
3588.	Windows	Serviceable. Aluminum frame; Casement.
3589.	Heat / Cooling Source	Serviceable. Central heating/cooling.
3590.	Electrical	Serviceable.
3592.	Bedroom Comments	None.

Duncan Inspection Services**Bedroom #2**

Step #	Component	Comment
3581.2.	Location	Left center.
3582.2.	Floors	Serviceable. Vinyl.
3583.2.	Walls	Serviceable. Paneled.
3584.2.	Ceilings	Serviceable. Paneling.
3585.2.	Ceiling fan	Not Present.
3586.2.	Doors	Serviceable. Hollow core.
3587.2.	Closet / Wardrobe	Serviceable. Hollow core sliding.
3588.2.	Windows	Serviceable. Aluminum frame; Casement.
3589.2.	Heat / Cooling Source	Serviceable. Central heating/cooling.
3590.2.	Electrical	Serviceable.
3592.2.	Bedroom Comments	None.

Duncan Inspection Services**Walkthrough Checklist****Final Walkthrough Pre-Closing Checklist ©**

Please use our complimentary pre-closing checklist on your final walk through of the property. There is a time period between our inspection and closing that varies with each property. Systems can fail at any time and defects can become visible under different viewing conditions (weather change, belongings removed etc.) so we urge you to operate all systems prior to closing and check all areas that may have been hidden from view due to occupant belongings or other obstructions.

- ☐ Obtain all operational manuals, well/septic records, records of sale (disclosure statement, offer to purchase, and closing documents), warranties and receipts for recent repairs. Keep them in a file.
- ☐ Check the exterior. Pay particular attention to the roof, especially if there has been a storm since the inspection. Run the sprinklers if weather permits.
- ☐ Check all interior rooms. Check for moving damage if the homeowner moved out between the inspection and closing. Operate all windows and doors and check for broken thermal pane seals, loose hardware, etc. Check ceilings for water stains.
- ☐ Check countertops and interiors of all drawers, cabinets and closets.
- ☐ Check all areas that may have been inaccessible during the inspection due to personal storage, furniture, area rugs, etc. and check items we don't review such as cosmetic concerns, alarms, intercoms and sound systems.
- ☐ Operate all systems/appliances, and the garage door. Obtain door transmitters. Do not operate air conditioners if the temperature is below 65 degrees. Check lights (Bring a couple of light bulbs to check inoperable light fixtures).
- ☐ Run all faucets and toilets. Fill tubs and sinks. Check for leaks. Run whirlpool tubs.
- ☐ Check basement and/or crawl space. Look for active stains and leaks at walls, floors and under and near plumbing.
- ☐ Check for signs of pests. Many folks do preventative pest control before taking occupancy.
- ☐ If possible, check inside of the attic.
- ☐ Verify that the seller has correctly completed any promised repairs (look at receipts, permits, etc).
- ☐ Verify that the seller has notified you of any changes in the condition of the property since the inspection.
- ☐ If you haven't purchased a home warranty, check with your agent and consider purchasing one.

We would like to thank you for allowing us to work with you and we wish you the very best in the future. Don't forget that our technical and do-it-yourself browsing library is at your disposal. Remember that we are here for advice at anytime. Whether it's counsel on something that breaks down or suggestions on a remodeling project, feel free to give us a call. Finally, please don't hesitate to recommend us to your friends•”we won't mind a bit!

The Appreciative Staff of Duncan Inspection Services



7/16/2026

SUMMARY REPORT

Page 31 of 33

Duncan Inspection Services
1224 Cardiff Ct
Modesto, CA 95350
Ph#: (209) 470-7732

SUMMARY ITEMS

Inspection #: 202607-08243
Dwelling Address: 8200 Jantzen Rd #201
Modesto, CA 95357

Client Name: Christopher Nall
Inspector: Duncan Lyons

This Summary Report of the limited visual, general home inspection was performed in accordance with the NAHI and/or ASHI Standards of Professional Practice for Certified Home Inspectors and as such is designed as an 'overview' of the full report and is provided to highlight only those findings that we feel are potentially significant in nature from a cost or safety standpoint and/or is in need of repair or replacement. This summary is provided as a courtesy and cannot be considered as a substitute for reading the entire report; we strongly recommend reading the full report before issuing any request for repairs. We will not be held liable for any omissions in the summary or the failure of our Customer to read the full report before issuing any request for repairs. *Please note that it is at the Client's discretion to have the possible problem reviewed to determine the cause and any recommended repairs or replacements should be completed by qualified and/or licensed professionals, prior to closing. This Report may contain digital photographs of some items and components and are for your convenience only and do not represent all items or components that are or may be deficient.

Exterior

1123. Stairs **Review.** Missing balusters and handrail observed. This is a "Safety Concern". Recommend review by a licensed professional for repair as necessary.

Electrical

1607. Smoke Detectors **Review.** None observed, suggest installing smoke detectors, as necessary, for safety.

1608. Carbon Monoxide Detectors **Review.** No carbon monoxide detector(s) noted. We recommend installing carbon monoxide detectors according to manufacturer's specifications and local ordinances to provide protection to occupants from potential poisoning from fossil fuel burning appliances, including fireplaces.

Crawlspace

2303. Walls **Review.** Metal skirting. Damaged areas observed. Recommend review by a licensed/qualified professional for repair or replacement as necessary.

Duncan Inspection Services
1224 Cardiff Ct
Modesto, CA 95350
Ph#: (209) 470-7732

2306. Support Posts /
Columns

Review. Wood rot, moisture damage observed under bathroom area, review by a licensed professional is needed for corrections as needed prior to close.

2310. Insulation

Review. Loose/missing sections observed in crawlspace, suggest securing or replacement as necessary.

2313. Visible
Plumbing

Review. Leaking observed at bathroom. Recommend review by a licensed plumber for repair or replacement, as necessary.

Kitchen

3108. Electrical

Review. Ground Fault Circuit Interrupters (GFCI) may not have been required when the home was built. Suggest client consider upgrading with GFCI's at all receptacles near water sources, such as the kitchen, the bathrooms, the garage, and exterior receptacles to enhance safety. Upgrades should be performed by a licensed electrician.

Bathroom

3222. Toilet

Review. The toilet bowl is loose at floor anchor bolts. The wax ring inside the unit must have a snug, secure fit in order to keep from leaking. Properly resealing and re-securing this unit is suggested to prevent water leakage and damage to the sub-floor area. This type of damage is not always visible or accessible to the inspector at time of inspection. Recommend review by a qualified plumber for repair or replacement, as necessary.

Laundry Area

3402. Walls

Review. Moisture damaged trim and wall observed. The extent of damage could not be determined without destructive analysis (maintenance and/or repairs should be performed). Suggest reviewing latest pest control report for a more detailed evaluation. See page 4 of full report for further information regarding water entry and growth.



7/16/2026

SUMMARY REPORT

Page 33 of 33

Duncan Inspection Services
1224 Cardiff Ct
Modesto, CA 95350
Ph#: (209) 470-7732

Dining Room

3527. Windows **Review.** Dry rot observed at window sill. Recommend further review for repair as necessary.

Living Room

3547. Windows **Review.** Window lock(s) is missing at driveway side window. Corrections are needed for security.

3549. Electrical **Review.** Ungrounded receptacles observed in the living room. Suggest review by licensed electrical contractor for repairs/replacements as needed to ensure safety.