



## VISUAL ROOF INSPECTION

MAY 05, 2026

**True Roof Inc. - We Put Integrity on Top.  
Inspection - Repair - Restoration - Replacement**

**rafael@trueroofca.com  
2095525682**

## GREEN VALLEY HOMES

8200 Jantzen Road  
Modesto, CA  
95357  
(408) 833-4986

# TERMS & CONDITIONS

**EXCLUSIONS:** Any additional layers of roofing system or damages found beneath the roof deck will be listed on a supplemental report with additional costs/findings. All change orders will be submitted in writing with necessary approval to continue work progress. Low sloped areas adjacent to standard slopes are commonly called a "hog valley." These areas of the roofing system cannot be determined to be leak free due to the slope having a high-risk of water intrusion. All hog-valleys, if present, are exempt from two year certification. All areas under solar panels, if present, are inaccessible to the inspector, therefore these areas are exempt from this roof inspection and two-year certification. The HVAC plenum flashing, if present, is an item that is exempt from inspection due to the inaccessibility beneath the roof covering. True Roof recommends hiring a licensed HVAC contractor to properly inspect the integrity of the HVAC unit and plenum flashing. Skylights, if present, may appear to be roofed properly, however, skylights are exempt from two-year certification due to them being mechanisms with multiple components, and a leak in these areas may not be determined until rain is present. All low-slope areas with a pitch of less than 3:12, if present, are exempt from two-year certification including porch and patio covers. Damage to wood sheathing is NOT covered in this roof inspection report unless a pest inspection report is sent to True Roof for comprehensive bid of damage wood under eaves and overhangs prior to inspection. Any foot traffic on the roof, other than that of employees and authorized individuals for True Roof, will void active roof certification.\*It is the responsibility of the homeowner to keep the roofing system free of debris during the winter months. Leaks caused by debris build-up are not covered under two-year certification. All certifications on the roofing system will be voided if repairs are made by other parties after certification has been given. True Roof is not responsible for leaks that may be caused by others after True Roof has completed repairs.

**Roof deck notice:** County/City building code may require new plywood to be installed over the existing substrate if the gaps between the substrate are 1/8" or more in size. If so, the additional cost to install new OSB will be listed on a change order and must be approved prior to continuance of the replacement. True Roof recommends factoring in this total when considering the estimate.

**Client Responsibilities:** Solar panels, if present must be contracted to be removed prior to reroof and reinstalled upon completion at the expense of the homeowner. True Roof is not responsible for this work or any fees associated. Satellite dishes installed on the roof will be required to be removed and is recommended to be reinstalled on the fascia/barge rafter by the satellite provider. True Roof is not responsible for this work scope or reattachment fees/reposition fees.

**NOTICE: \*All damaged wood discovered after removal of the roof covering including but not limited to: fascia, plywood sheathing, shiplap sheathing, hardwood sheathing, rafters, rafter-tails, and fascia, will be removed and replaced at a rate of \$85 per man-hour, plus the cost of materials used and 30%. In some areas, overhangs may be cut-back to a shorter length in order to properly repair the structure in an economical manner when applicable.**

## Cancellation Notice

You may cancel this contract from the day you enter into the contract until 3 days after you receive a copy of the contract. You do not need a reason to cancel. There are other grounds for extended cancellation. For more information, you may contact your provincial/ territorial consumer affairs office. If you cancel this contract, the seller has 15 days to refund your money and any trade-in, or the cash value of the trade-in. You must then return the goods. To cancel, you must give notice of cancellation at the address in this contract. You must give notice of cancellation by a method that will allow you to prove that you gave notice, including registered mail, fax or by personal delivery.

## Mechanics Lien Clause

California Business & Professions Code §7018.5 and §7159

"Under the California Mechanics Lien Law, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer to satisfy the lien. If a lien is filed against your property, you may have to pay twice or face the forced sale of your property. To preserve their right to file a lien, certain claimants such as subcontractors or material suppliers are required to provide you with a document called a 'Preliminary Notice.' This notice is not a lien. The purpose of the notice is to let you know of persons

I acknowledge that I have read and understand this page. Initials: \_\_\_\_\_

or companies who may have a right to file a lien against your property if they are not paid.”

I understand that I must remove items from the interior walls of my home that may be damaged or fall due to vibrations from the loading/installation of shingles on to my roof (if applicable), or installation of siding. True Roof Inc. is not liable for such damages.

I understand that minor stucco damage may result when the roof is torn off areas where stucco meets my roof's surface, especially where improperly applied. True Roof Inc. is not liable for repairing said damage.

I understand that any warranty for material used during the project is provided by the material manufacturer. Unless agreed upon otherwise, True Roof Inc. provides a 10-year Workmanship Warranty on portions of the project in which True Roof Inc. fully replaced any existing products.

I understand that, unless agreed upon. This does not apply to products, some of which may deteriorate more rapidly (ie. sealants) and should be inspected on a regular basis, and am not responsible for material shortage and have no claim to material surpluses.

I certify that I am the registered owner of the above project property, or have the legal permission to authorize True Roof Inc. to perform the work as stated and agree to pay the total project price.

I understand that any insurance claims are subject to the specific terms and conditions outlined by my insurance company, and may be subject to insurance company approval.

I understand that payment in full is due upon completion of work as stated in contract. All invoices not paid in full after 15 days will be subject to a 2% per month interest charge.

I understand that approval of my estimate is subject to customer credit approval by True Roof Inc.. I agree that True Roof Inc. may access my credit bureau report(s), trade references, and other credit information prior to granting credit approval.

**I acknowledge that I have read and understand this page. Initials:** \_\_\_\_\_

# INTRODUCTION

Hi Andrew,

## **Thank You for choosing True Roof Inc.**

We sincerely appreciate the opportunity to conduct a visual inspection of your roof. At True Roof, our mission is to deliver a comprehensive evaluation of your roof's condition by providing high-quality images, accurate assessments, and a detailed summary of its current state.

### **Scope of Inspection:**

- **Safety First:** Ensure safe access to all areas of the roof.
- **Perimeter Assessment:** Inspect the perimeter of the home to evaluate the substrate quality at eaves and gables.
- **Damage Identification:** Identify and document any damaged wood or structural issues caused by roof leaks or water intrusion.
- **Roof Access:** Access the roof (when safe and feasible) to capture photographic evidence of critical conditions.
- **Roof Covering Analysis:** Determine the type of roof covering, number of layers\*, and approximate age using available resources such as permit history or satellite imagery.
- **Condition Report:** Provide a detailed evaluation of the existing roof covering, including expectations for its remaining service life.
- **Recommendations:** Offer tailored options for maintenance, repairs, rejuvenation, or replacement, as appropriate.

Our goal is to provide you with a clear, professional understanding of your roof's condition and actionable steps to address any issues. If you have specific concerns, please let us know prior to the inspection so we can address them thoroughly.

Thank you again for trusting True Roof Inc. We look forward to assisting you!

Kind regards,  
Rafael Chavez  
rafael@trueroofca.com  
2095525682

# INSPECTION NOTES

## **Roof Information:**

Type: Metal

Color: White

Style: Mechanical Seams

Age: 15+ years

Layers: 1

Levels: 1

Pitch: 2:12

Certiifiable: With repairs

## **Findings:**

- **The roof is in need of a protective roof coating application due to visible deterioration of the existing roofing surface. Multiple areas throughout the roof system exhibit signs of aging, including surface splits, cracking, and general wear that have compromised the roof's ability to properly resist weather exposure and water intrusion. These conditions indicate that the existing surface protection has significantly degraded over time.**
- **Applying a high-quality roof coating system is recommended to help restore and extend the service life of the roof by providing an additional protective barrier against UV exposure, moisture penetration, and ongoing environmental wear. Prior to application, all affected areas should be properly cleaned and prepared to ensure proper adhesion and performance of the coating material. Any visible splits, cracks, or damaged sections should be addressed and sealed as part of the preparation process to create a uniform and watertight surface.**
- **Completion of the recommended roof coating service will help improve the overall condition, performance, and longevity of the roofing system while reducing the likelihood of future leaks and premature deterioration.**

**Please click here to view full photo library of your roofing system!**

**Link:**<https://app.companycam.com/galleries/ZHj3J5vK>

**Exclusions:** Areas under solar panels are not inspected visually, these areas are exempt from two-year certification. Areas with a pitch of less than 3:12 are not covered under two-year certification unless a roof restoration or new roof is installed by True Roof in these areas. Skylight assemblies are not included in two-year certification. Damaged wood repairs beneath the roof covering is not included in repair costs unless explicitly stated in the following scope of work.

The items below are recommended repairs that are required to be completed prior to obtaining two year certification, if eligible. Each line item represents a recommendation that your roofing system requires to prevent water intrusion (either active or preventative).

Routine maintenance repairs should be considered every 2-3 years.

# SILICONE COATING - 15 YEAR WARRANTY

## Description

### Roof Preparation

#### Pressure Wash - Roof Restoration Prep

Pressure Washing the roof covering to ensure all loose debris and foreign materials are cleared away from the roofing system. The only way to ensure a positive bond is to start with a clean surface.

### Coating Application

#### Spot Repair Roof Covering

Identify all splits, cracks, blisters, and buckles in the roof surface and treat these areas with acrylic mastic and polyester fabric, as needed.

#### Three-Course Penetrations

Three-Course all penetrations in the roofing system with ASC-1 Elastomeric Coating and polyester fabric.

#### Spray Apply Base Primer - (1/2 GPS)

Apply base primer over the entire roof deck to ensure proper adhesion of coating application above. Application rate: .5 gallons per 100sf.

#### Apply Silicone Coating -

Roll apply high-solids silicone coating at a rate of 1.5 gallons per 100sf per application. Each application must be applied perpendicular to the previous pass.

Application rate to be 3 gallons per 100sf for 20 year specification on BUR.

#### Repair Ponding Areas

All ponding areas of the roof covering to be coated with acrylic elastomeric coating and fully saturated in 40" polyester fleece. A top-coat of high-solids silicone is necessary in all areas where ponding water is noted.

### Materials Required for Restoration

#### ASC 7 ElastoMagic 3.5G

Acrylic Mastic for detail work.  
3.5 gallon pail

#### ASC P-1000 Silicone Primer

ASC P-1000 Silicone Primer

#### ASC F Polyester Standard Firm Roll Fabric

ASC F Polyester Standard Firm Roll Fabric

#### ASC S Silicone Roof Coating

ASC S Silicone Roof Coating

**Estimate subtotal** \$7,170.64

**Total** \$7,170.64

# SIGNATURES PAGE

**Silicone Coating - 15 Year Warranty**

\$7,170.64

**Name:** Andrew Quintong

**Address:** 8200 Jantzen Road, Modesto, CA

Any repair costs greater than \$3,000 will require a 10% deposit upon scheduling work.

---

## Customer Comments / Notes

---

**Andrew Quintong:**

**Date:**

---

# AUTHORIZATION PAGE

Accepted By: \_\_\_\_\_ Date: \_\_\_\_\_  
Signature: \_\_\_\_\_

Billing Party Mailing Address: \_\_\_\_\_ Billing Party Email: \_\_\_\_\_  
Billing Party Phone Number: \_\_\_\_\_

Building Owner: \_\_\_\_\_ Owner's Email: \_\_\_\_\_  
Owner's Phone Number: \_\_\_\_\_

## **Billing Through Escrow:**

Title Co: \_\_\_\_\_ Officer: \_\_\_\_\_ COE Date: \_\_\_\_\_  
Phone: \_\_\_\_\_ Email Address: \_\_\_\_\_  
Escrow # \_\_\_\_\_

**Sign and return this form to TRUE ROOF for scheduling repairs.**

# INSPECTION PHOTOS



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>



Photo By: Rafael Chavez // Project:  
<https://app.companycam.com/projects/104641802>